


COMANCHE ACC IMPROVEMENT PROJECT




Xcel Energy – Comanche Station Pueblo, Colorado


- **Coal Fired Plant**
 - **(2) 350 MW (Units 1 & 2)**
 - **(1) 800 MW (Unit 3)**
 - **Unit 3, Utilizes Hybrid Cooling with a GEA 45 Cell, 9X5 ACC**
 - **Unit 3, Commercial Operation July 2010**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of gray and yellow, creating a sense of motion and flow.




Discussion Topics

- **ACC Issues During Start-up**
 - **ACC Challenges After Commissioning**
 - **Fan Blade Attachment**
 - **Fan Blade Cracking**
 - **Gear Box Modifications**
 - **Addition of Fan Shroud Stiffening Rings**
 - **Installation of a Wind Screen and Structural Bracing**
 - **Tube Cleaning**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of grey and yellow, creating a sense of motion or a stylized horizon.


ACC Challenges During Start-up

- **Vacuum Leaks Within the Condensate System**
 - **Mechanical Failures of Gear Box Oil Pumps and Pump Couplings**
 - **Input Shaft Seal Leaks**
 - **Output Shaft Seal Leaks**
 - **Wind Milling of Fan Blades in the Reverse Direction of Normal Rotation**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of grey and yellow, creating a sense of motion or a stylized horizon.


ACC Challenges After Commissioning

- **Howden Fan Blade Attachment Fan/Hub Loosening Problems**
 - **Howden Fan Blade Cracking Issues**
 - **Continued Input and Output Shaft Seal Leaks**
 - **Continued Oil Pump/Coupling Failures**
 - **Loss of Interference Fits on Shafts for Bearings and Bull Gear**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of grey and yellow, creating a sense of motion or a stylized horizon.


ACC Challenges After Commissioning

- **Oil Leaks via the Output Shaft Keyway**
 - **Overheating of the Gear Box Oil**
 - **Switching from Mineral Based Oil to Synthetic**
 - **Under Designed Hoists and Monorail Beams on all 9 Streets**
 - **Inoperative Tube Cleaning System**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of grey, yellow, and orange, creating a sense of motion or a stylized horizon.

GEA Engineering Study

- **Due to the Ongoing Problems, GEA Conducted an Engineering Study with GEA State Side and European Engineers**
 - **On Site Evaluation of the present ACC, Structure, etc. was completed**
 - **Recommendations submitted to Comanche from GEA**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of gray and yellow, creating a sense of motion or a stylized horizon.

ACC Resolutions – Fan Blades

- **Fan Blade Attachment Modification**
 - **Fan Blade Cracking Minimization and Increased PM Program**
 - **Installation of a Personnel Protective Fence**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of gray and yellow, creating a sense of motion or a stylized horizon.


Re-Designed *Blade Clamp*



Cracked Blade



Catastrophic Blade Failure




Perimeter Fence



ACC Resolutions – Gear Box Lifting


- **Engineering Evaluation of the Monorail Lifting Beams**
- **Stiffening of the Monorail Beams on all 9 Streets**
- **Elimination of the 2 Ton Hoist and Purchase and Installation of 3 Ton Electric Hoists on all Streets**



3 Ton Monorail Hoist



ACC Resolutions – Gear Box Failures

- **Combined Effort Between Amarillo Gear, In-Pro Seal, Chesterton Seal and Comanche**
 - **Addition of Extended Bearing Housings with Carrier Bearings**
 - **Modification of the Input Shaft Lip Seal to an In-Pro Mechanical Seal with New Seal Carriers**
 - **Modification of the Output Shaft V-Seal to a Reinforced Viton Seal**
- 

Motor and Gear Box



Motor Removal



Motor on Stand




Fan Hub Removal



Fan Removed



Lowering Gear Box




Machining Output Shaft



Dimensional Check



Knurling Output Shaft



Output Shaft Extension Housing




Extension Housing Flange



Installation of Extension Housing




Carrier Bearing Housing



Old Style Input Shaft Lip Seals



Output Shaft Seal Can



New & Old Output Shaft Lip Seal



Hub Gear Heating



*Hardened Anti-Rotation
Plate Installed*



Bull Gear Installation




Output Shaft Installation



Input Shaft, In-Pro Seal



In-Pro Seal Installed



ACC Resolution – Gear Box Failures

- **Redesigned Retaining Ring on Top and Bottom of Hub Gear Utilizing an O-ring to Eliminate Keyway Oil Leaks**
 - **Removal of the Shaft Driven Oil Pumps**
 - **Addition of Externally Mounted Viking Electric Driven Oil Pumps**
 - **Changed to Synthetic Oil rather than Mineral Based**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of gray and yellow, creating a sense of motion or a stylized horizon.

Hub Gear Retaining Rings



Old Shaft Driven Oil Pump



Shaft Driven Oil Pump Wear Area



Elec. Oil Pump Modification Plate



Viking Electric Oil Pump



Oil Pump



Output & Intermediate Shaft Install



Gear Box Upper Case



Completed Gear Box




Gear Box Staged for Installation



Gear Box Lift




Gear Box Installation




Gear Box In Place



Motor Housing Installed




ACC Resolutions – Gear Box Failures

- **(6) Month Oil Sampling Program**
 - **On-line Filtering Program**
 - **(6) Month PM Program for Blade Torque, Blade Crack Inspections and Gear Box Bolting**
 - **Seasonal Shut Off of Gear Box Heaters**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of grey and yellow, creating a sense of motion or a stylized horizon.

Gear Box Oil Heater Fouling




ACC Resolutions – Fan Shrouds

- **GEA's Engineering Study Concluded Excessive Fan Shroud Movement**
 - **Evaluated Stiffening Ring Quotes from Howden**
 - **Utilized a Local Contractor to Fabricate and Install Stiffening Rings**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of grey and yellow, creating a sense of motion or a stylized horizon.

Fan Shroud Stiffening Ring



ACC Resolutions – Wind Screen Installation

- **Goal was to Minimize Fan Blade Cracking**
 - **Worley-Parsons Engineering Study Conducted on the ACC Structure**
 - **Results Concluded that Extensive Cross Bracing was needed for any type of Wind Screen Material**
 - **Bracing Installed**
 - **Non-movable Screen Installed**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of gray and yellow, creating a sense of motion or a stylized horizon.


ACC Wind Screen Installation




ACC Wind Screen Installation



ACC Resolutions – Tube Cleaning

- **Tube Cleaning System Was Never Completed and Commissioned by Shaw**
 - **Extensive Oil Film on Tubes from Seal Leaks Which Increased the Amount of Dirt and Build-up on Tubes**
 - **Significant Performance Loss of ACC Due to Lack of Cleanliness**
 - **Tube Cleaning Performed Summer 2013**
- 
- The bottom of the slide features a decorative graphic consisting of several overlapping, wavy lines in shades of grey, yellow, and orange, creating a sense of motion or a stylized horizon.

Tube Cleaning



Questions?

