



ACC gearboxes – Eskom's experiences of the last 20 years

ACC Users Group 2017

October 2017

Presented by Ockert Augustyn

Content



- Eskom's ACC fleet
- Various gearbox configurations
- Problems encountered
- Remedies
- Alternatives
- Conclusions



Medupi U6

Eskom's ACC fleet - MEDUPI



- 250 km north of JHB
- U6 commissioned in 2014/2015
- 3 operational units currently
- 64 gearboxes/unit (8 x 8 streets)
- 6 x 794 MW
- Motor power: 225 kW

Eskom's ACC fleet - MEDUPI





Eskom's ACC fleet - KUSILE



- 100km east from JHB
- U1 commissioned in 2016
- 1 operational unit currently
- 64 gearboxes/unit (8 x 8 streets) 2 fan designs
- 6 x 800 MW
- Motor power: 250 kW + soft starters


Eskom's ACC fleet - MATIMBA



- 5 km from Medupi
- First unit commissioned in 1987, last in 1991
- 48 gearboxes/unit (8 x 6 streets)
- 6 x 665MW
- Motor power: 270 kW
- 10% stall margin on fans

Eskom's ACC fleet - MATIMBA





Eskom's ACC fleet - MAJUBA



- 250 km south east of JHB
- First unit commissioned in 1996 (construction began in 1983), last in 2001
- 48 gearboxes/unit (8 x 6 streets)
- 3 x 657MW
- 3 units wet cooled (3 x 713 MW)
- Very similar design to Matimba

Eskom's ACC fleet - MAJUBA





Eskom's ACC fleet - MAJUBA








- 9 different types of gearboxes > 1200+ gearboxes
- 3 manufacturers
- Casing Mono and split-casing
- Lubrication splash and force feed
- Oil mineral and synthetic
- Fan bridge layout differences












Space for movement and maintenance activities

Monorail?
















Layout considerations

- Position of gearbox influences the monorail position
- Fan grating should allow for maintenance
- Walkway mass ratings
- Maximize airflow over the gearbox
- Getting Oil to 45-60m level very time consuming
- Retrofits in the future?



Working conditions

- Adverse weather conditions (wind, up to 45°C ambient)
- ACC design unknowns/flaws (eg. Matimba)
- High production demand > less maintenance
- Increase blade angles > increase load on gearbox (+ oil)
- Poor cooling of casing (i.e. oil) due to configuration/fan design
- Increased fan power consumption
- Step sequencing of fans (new build fleet)



Gearbox failures







Gearbox failures








- Matimba gearbox failures
 - 48 gearboxes procured in 2009
 - 8 months later first catastrophic failures
 - Multiple problems:
 - Micro pitting
 - 40% of oil pumps failed
 - Similar trends at Medupi experienced already



Matimba gearbox failures






Fan shaft failures




Fan shaft failures





High oil temperatures







- Backstop > oil leaks
- Logic start/stop sequencing
- Oil seal leaks & over filling
- Safety concerns (e.g. loose blades/fan assemblies)
- Local manufacturing concerns (i.e. quality)




General failures

- Mostly intermediate gears
- Most probably due to pitting due to high loads
- High temperatures means oil viscosity too low
- Changed from grade 220 to 320



Oil leaks






Oil pump failures

- 40% of oil pumps failed
- ODS analysis indicated continuous distortion of gearbox casing under the motor weight.
- Resulted in deflection of shaft driving oil pump
- Stiffening cradle was installed and significantly reduced oil pump failures

Research & Remedies








High Oil temperatures

- Continuous operating temperatures of ~100°C [~210 °F]
- 160 liter oil sump [42 US gallons]
- Oil replacement twice a year
- Project initiated to install coolers which will circulate the oil through small radiator
- Reduce oil temperature 60°C

Alternatives?





- Direct drive motor
- No oil required, VSD
- Operational at Dry Fork
- 30% heavier

Conclusions



- Oil Mineral vs Synthetic
- Lubrication mechanisms force feed vs self lubricated
- Maintenance
 - Split case found to be easier to maintain
 - Mono blocks require hydraulic press
- Life cycle costs (options differ by up to ~40%)

Acknoledgements



- Francois Nel
- Hein Goldschagg





Questions